

Material Safety Data Sheet

Identity: SOFT TRAY

SECTION I

| | |
|-----------------------------------|--|
| Manufacturer: | Gresco Products, Inc. |
| Address: | 13391 Murphy Road - Stafford, TX 77477 |
| Emergency Telephone Number: | None |
| Telephone Number for Information: | (281) 261-1811 |
| Date Prepared: | July 26, 2004 |

SECTION II & III - Hazardous Ingredients & Physical/Chemical Characteristics

| | |
|---|-----------------------------------|
| Hazardous Components (As Defined by CFR 1910.1200): | Vitreous Aluminosilicate Fibers |
| Exposure Limits: | Not known |
| Boiling Point: | Not Known |
| Vapor Pressure (mm Hg.): | 0 at 20°C |
| Vapor Density (Air = 1): | 1 |
| Specific Gravity (water = 1): | 2.7 g/cm ³ |
| Melting Point: | 1790°C/3260°F |
| Evaporation Rate (Butyl Acetate = 1): | less than 1 |
| Solubility in Water: | Insoluble |
| Appearance and Odor: | White, fluffy appearance, no odor |

SECTION IV - Fire and Explosion Data

| | |
|-------------------------------------|---------------|
| Flash Point (Method Used): | Will not burn |
| Flammable Limits: | None |
| Extinguishing Media: | None needed |
| Special Fire Fighting Procedures: | None required |
| Unusual Fire and Explosion Hazards: | None known |

SECTION V - Reactivity Data

| | |
|---|---|
| Stability: | Stable |
| Incompatibility (Materials to Avoid): | Contact with powerful oxidizers may cause fires. Avoid contact with strong acids: especially Hydrofluoric Acid. |
| Hazardous Decomposition or By Products: | The byproduct of silica and Hydrofluoric Acid is silicon tetra fluoride, a highly corrosive gas. |
| Hazardous Polymerization: | Will not occur |

SECTION VI - Health Hazard Data

| | |
|--|---|
| Routes of Entry: | |
| inhalation?: | Yes |
| skin?: | No |
| ingestion?: | No |
| eyes?: | No |
| Health Hazards (Acute and Chronic): | Prolonged exposure to the fibers or dust from this material may cause lung damage. |
| Carcinogenicity: | |
| IARC Monographs?: | Possible - class 2B - Sufficient evidence for carcinogenicity in experimental animals; no human epidemiological data |
| Signs and Symptoms of Exposure: | Coughing, wheezing, sputum production. |
| Medical Conditions Aggravated by Exposure: | Pre-existing diseases of the eyes, lungs, and skin |
| Emergency and First Aid Procedures: | Ingestion: Do not induce vomiting, consult physician if symptoms develop. Eye contact: flush with water; avoid rubbing eyes, consult physician. Inhalation: remove person from source of exposure, consult physician. |

SECTION VII - Precautions for Safe Handling and Use

| | |
|--|---|
| Steps to Be Taken in Case Material is Released or Spilled: | Wipe up with dampened cloth |
| Waste Disposal Method: | Dispose in accordance with local, state, and federal regulations. |
| Precautions to Be Taken in Handling and Storing: | Avoid over handling (to minimize dust) |
| Other Precautions: | Avoid breathing fumes that may be given off during initial firing |

SECTION VIII - Control Measures

| | |
|---|--|
| Respiratory Protection: | Recommended when handling material |
| Ventilation: | Recommended |
| Protective Gloves: | Optional |
| Eye Protection: | Optional |
| Other Protective Clothing or Equipment: | None required |
| Work/Hygienic Practices: | Avoid over handling (to minimize dust) |